






FIGURES






















PLATES



Plate 1: General overview of Quarry Spoil Tip looking towards the south.



Plate 2: General overview of quarry (Q1) towards the western flank with quarry spoil mound in the foreground.

PLATES



EARTH SCIENCE PARTNERSHIP



Plate 3: Eastern flank of the quarry (Q1) looking towards the northeast.



Plate 4: Existing access track to the rear of Godre'r Graig Primary School

PLATES



EARTH SCIENCE PARTNERSHIP



Plate 5: Looking towards the south along access to lower slopes.



Plate 6: Looking downslope towards the south, vegetation clearance of survey

PLATES



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taff's Well, Cardiff CF15 7RB Tel: 029 2081 3385

enquiries@earthsciencepartnership.com



Plate 7: Looking towards the west across area of vegetation clearance on the upper survey line (perpendicular to slope).



Plate 8: Looking towards the west across area of vegetation clearance on mid-slope survey line (perpendicular to slope). Cobbles and boulders visible on site surface in foreground. Location of BH04.

PLATES



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB

Tel: 029 2081 3385 enquiries@earthsciencepartnership.com



Plate 9: Looking upslope towards the north across area of vegetation clearance at base of slope.



Plate 10: Overview of access track through former Cwar Pen-twyn Quarry (Q2), looking towards the west.

PLATES



EARTH SCIENCE PARTNERSHIP



Plate 11: Overview of access track beyond former Cwar Pen-twyn Quarry, looking towards the west.



Plate 12: Overview of access track to area of site investigation and upper survey line (perpendicular to slope), looking towards the west.

PLATES



EARTH SCIENCE PARTNERSHIP



Plate 13: Quarry spoil cobbles and boulders visible on ground surface.



Plate 14: Looking downslope towards the south, potentially anthropogenically modified mound, approximate edges indicated by red dashed line.

PLATES



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taff's Well, Cardiff CF15 7RB Tel: 029 2081 3385

enquiries@earthsciencepartnership.com



Plate 15: Stream 2 identified on site, no further evidence of stream up slope. Looking towards the northwest.



Plate 16: Looking downslope to the west, saturated ground with streams flowing from base of spoil tip.

PLATES



EARTH SCIENCE PARTNERSHIP



Plate 17: Coal visible on ground surface along access track, looking towards the northeast. Coal located nearby historic mine entry (M1) and quarry (Q3)

PLATES



EARTH SCIENCE PARTNERSHIP