



Legend

- Assessment Area
- Inspection Route June 2019
- Inspection Route Jan 2020

Spoil Type

- Coal Waste
- Quarry Waste

Geomorphology

- Concave change in slope
- Sharp ridgeline
- Concave break in slope
- Break in slope
- Convex change in slope
- Convex break in slope
- Rounded spurline
- Sharp spurline
- Rounded ridgeline
- Slope Angle
- Drainage line

Inspected API landslides

- Confirmed
- Not evident
- Talus
- Tension Crack
- Outcrop
- Quarry
- Godrergraig Landslide
- Adit
- ⊗ TP
- ⊕ BH

Notes:

Figure 5: Engineering Geological Map

PROJECT:
 GODRE'R GRAIG VILLAGE, TAWE
 VALLEY

Scale: AS SHOWN

FIGURE 5:
 ENGINEERING GEOLOGICAL MAP

EARTH SCIENCE PARTNERSHIP
 33 Cardiff Road, Taffs Well,
 Cardiff CF15 7RB Tel: 029 2081 3385
 enquiries@earthsciencepartnership.com